	9082 2245Z 29 APR 63	TOP SECRET	<u> </u>	5 G
25X1	DIRECTOR		SOLUTION CONTRACTOR OF THE SOLUTION CONTRACTOR O	
	ansion: OPS (1,2,3,4,5,6)		OPERAZI	DIONAL IMMEDIATE
	TOR 2306Z 29 APR 6	3	Monada of Congress of Administration	
25X1 25X1		PRITY	lecel.	IN 74225 0012 Ceg)
25X1	A. 1109 B29/2125 C. MSN PARTIAL SUCC		$\frac{29/2^3}{0 \text{ Loss of PF}}$	
		OOD. INTERMITTENT COMP. FAILED, ALL SYSTEMS APP.		•

CAMERA IN COCKPIT APPARENTLY FROZE-DID NOT EXPOSE FILM.

D. NONE. RMKS: PRESENTLY PLAN TO LAUNCH 1110 AS SCHED. HATCH

HTR NOT REQUIRED, BELIEVE REPLACEMENT OF PRESS REGULATOR WILL TAKE

CARE OF PRESS PROBLEM.

END OF MESSAGE